

HPI Bucket Seat Exclusive Seat Rail

Please let us know whether your vehicle is right-hand drive (RHD) or left-hand drive (LHD) when placing your order.

Vehicle	Right (Driver Side) Part Number	Left (Passenger Side) Part Number	Compatible Vehicles	Side Airbag Canceller Resistance Value	Seating Position	Seat Sensor Offset	Note
RZ34 Z34 Fairlady Z	n090rd	n090ld	RZ34 Z34 2008.12~	2.2Ω *Sold separately	Approx. 40mm lower than stock	Offset approx. 20mm toward the door	
EK2, EK3, EK4, EK9, EJ7 Civic	H019RD_	H019LD_	Civic EK# (Sep 1995 – Sep 2000) Civic Coupe EJ7 (Jan 1996 – Aug 1997)	None	Approx. 50mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
JW5 S660	H093RD	H093LD	S660 JW5 2015.4~2021.12	2.0Ω *Sold separately	Approx. 45mm lower than stock	Offset approx. 10mm toward the door	
EF1 EF2 EF3 EF9	H003RD	H003LD	Civic EF# (Sep 1987 – Sep 1991)	None	Approx. 60mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
EG3, EG4, EG6, EG7, EG8, EG9, EJ1, EJ2, DC1, DC2, DB6, DB7, DB8 Civic / Integra	H006RD	H006LD	Civic EG# (Sep 1991 – Aug 1995) Civic Ferio EJ1/EJ2 (Sep 1991 – Aug 1995) Civic Ferio EJ1/EJ2 (Sep 1991 – Aug 1995)	None	Approx. 50mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
ND5RC, NDERC, ND5RE, NDERE Roadster	ma046rd	ma046ld	Roadster ND#R# (May 2015 –)	2.0Ω *Sold separately	Approx. 50mm lower than stock	Offset approx. 10mm toward the door	

Vehicle	Right (Driver Side) Part Number	Left (Passenger Side) Part Number	Compatible Vehicles	Side Airbag Canceller Resistance Value	Seating Position	Seat Sensor Offset	Note
SE3P RX-8	MA037RD	MA037LD	RX-8 SE3P (Apr 2003 – Apr 2013)	2.0Ω *Sold separately	Approx. 50mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
FD3S	MA008RD	MA008LD	RX-7 FD3S (Oct 1991 – Aug 2002)	None	Approx. 30mm lower than stock	Offset approx. 20mm toward the door	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
ER34 HR34 C35	N045RD	N045LD	Skyline ER34 / HR34 (May 1998 – May 2001)	2.0Ω *Sold separately	Approx. 45mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
BNR34, ENR34, R33, R32, A31, CA31, C34, C33 Skyline / Cefiro / Laurel	N014RD	N014LD	Skyline BNR34 / ENR34 (May 1998 – Jan 2002) Skyline #R33 / #R32 (Aug 1989 – Apr 1998) Cefiro A31 / CA31 (Sep 1988 – Jul 1994) Laurel C34 / C33 (Dec 1988 – Jun 1997)	2.0Ω (BNR34 / ENR34) *Sold separately	Approx. 50mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
S13 S14 S15	N013RD	N013LD	Silvia / 180SX S13 (May 1988 – Jul 1993) Silvia S14 (Aug 1993 – Dec 1998) Silvia S15 (Jan 1999 – Aug 2002)	2.0Ω (S15) *Sold separately	Approx. 50mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.

Vehicle	Right (Driver Side) Part Number	Left (Passenger Side) Part Number	Compatible Vehicles	Side Airbag Canceller Resistance Value	Seating Position	Seat Sensor Offset	Note
R35	N070RD	N070LD	GT-R R35 (Dec 2007 – Sep 2025)	2.0Ω (S15) *Sold separately	Approx. 50mm lower than stock	Offset approx. 20mm toward the door	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
JZX100	t064rd		Cresta / Chaser / Mark II JZX100 (Sep 1996 – Oct 2000)	2.0Ω (S15) *Sold separately	Approx. 40mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
JZA80 JZZ30	T029RD	T029L	Supra JZA80 (May 1993 – Jul 2002) Soarer JZZ30 (May 1991 – Dec 2000)	None	Approx. 40mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.

Vehicle	Right (Driver Side) Part Number	Left (Passenger Side) Part Number	Compatible Vehicles	Side Airbag Canceller Resistance Value	Seating Position	Seat Sensor Offset	Note
GXPA16, KSP210, MXP##, MXPB15, and other Toyota models	T159R		GR Yaris GXPA16 (Jan 2020 – Mar 2024) Yaris KSP210 / MXP## (Feb 2020 –) Yaris Cross MXPB15 (Aug 2020 –) Corolla (including Sport / Touring) E21## (Oct 2019 –) Prius (including PHV) ZVW5# (Dec 2015 – Jan 2023) Camry AXVH70 (Jul 2017 – Dec 2023) C-HR NGX50 / ZYX10 (Dec 2016 – Aug 2023)	2.2Ω *Sold separately	GR Yaris: Approx. 20mm lower than stock Corolla: Approx. 10mm lower than stock Prius: Approx. 20mm lower than stock Camry: Approx. 20mm lower than stock C-HR: Approx. 15mm lower than stock	Offset approx. 10mm toward the door	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
ZN8 ZD8 ZN6 ZC6 GR86 86 BRZ	T130RD	T130LD	GR86 ZN8 (Oct 2021 –) (Right side / driver's side only) 86 ZN6 (Apr 2012 – Oct 2021) BRZ ZD8 (Aug 2021 –) (Right side / driver's side only) BRZ ZC6 (Mar 2012 – Mar 2021)	2.2Ω *Sold separately	Approx. 50mm lower than stock	Offset approx. 10mm toward the door	*ZN8 / ZD8 models are compatible with the right side (driver's side) only. *For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.

Vehicle	Right (Driver Side) Part Number	Left (Passenger Side) Part Number	Compatible Vehicles	Side Airbag Canceller Resistance Value	Seating Position	Seat Sensor Offset	Note
JB64W, JB74W, JC74W JimnyJB64W, JB74W, JC74W Jimny	S084R	S084L	Jimny JB64W (Jul 2018 -) Jimny Sierra JB74W (Jul 2018 -) Jimny Nomad JC74W (Apr 2025 -)	2.2Ω *Sold separately	Approx. 30mm lower than stock	None	For 2-door vehicles with rear seats, replacing both front seats simultaneously may require updating the official seating capacity.
ZC33S, ZC#3S, ZD#3S Swift	S080RD_	S080LD_	Swift Sport ZC33S (Sep 2017 -) Swift ZC#3S / ZD#3S (Jan 2017 -)	2.0Ω *Sold separately	Approx. 40mm lower than stock	None	